

REPLACEMENT FOR

**BUICK CENTURY '99
CHINA TYPE**

132-1101-LD

HEAD LAMP
R 92682
L 92683
PCS CFT



H1/H1/P21W/P21W/W5W

TBA

REPLACEMENT FOR

**BUICK CENTURY '03
CHINA TYPE**

132-1104-LD

HEAD LAMP
R
L
PCS CFT



H1/H7/W5W

TBA

REPLACEMENT FOR

**BUICK GL8 '94
CHINA TYPE**

132-1103-LD

HEAD LAMP
R
L 16530511
PCS CFT



H4/W5W

TBA

132-2001

FOR LAMP
R 10292680
L 10292681
PCS CFT



H3

TBA

'97

132-2002

FOR LAMP
R
L
PCS CFT



H3

TBA

132-1103-LDH

HEAD LAMP
R
L
PCS CFT



H4/W5W

TBA

132-1901

TAIL LAMP
R
L
PCS CFT



TBA

'2000

442-1402N-C

SIDE LAMP
100PCS 0.90CFT



WY5W

132-1501-U

CORNER LAMP
R
L 16530275
10PCS 4.64CFT



PY21W

132-1903

TAIL LAMP
R
L
PCS CFT



P21W/P21/5W/W5W

TBA

132-1902

TAIL LAMP
R
L
10PCS CFT



TBA



REPLACEMENT FOR

**BUICK GL8 '99
CHINA TYPE**



REPLACEMENT FOR

CAPERICE '00

REPLACEMENT FOR

LOVA '06

132-1102-LD
HEAD LAMP
R
L
PCS CFT



H4/PY21W/W5W **TBA**

332-11A3-U
HEAD LAMP
R 92048542
L 92055107
4PCS 4.98CFT



H4/H1/PY21W/W5W

235-1104-LD SA-TYPE
HEAD LAMP
R
L
PCS CFT



H4/PY21W/W5W **TBA**

132-1902
TAIL LAMP
R
L
10PCS CFT



TBA

TBA

132-1904
TAIL LAMP
R
L
PCS CFT



P21W/PY21W/W16W/P21/5W **TBA**

TBA

TBA

TBA

TBA

TBA

TBA

TBA










REPLACEMENT FOR

OPTRA '04

GM

<p>222-1114-LD-EM NUBIRA 1600 CC 1800 CC HEAD LAMP R 96458810 L 96458809 6PCS 6.73CFT</p>  <p>H1/H7/PY21W/W5W</p>		
<p>222-1114-LD-E NUBIRA HEAD LAMP R 96458814 R 96425288 L 96458813 L 96425287 6PCS 6.73CFT</p>  <p>H1/H7/PY21W/W5W</p>		
<p>235-1402N-AE SIDE LAMP M1A032D1 96337460 PCS CFT</p>  <p>WY5W TBA</p>		
<p>222-1914-UE NUBIRA 1600 CC TAIL LAMP R 96551226 L 96551225 6PCS 4.69CFT</p>  <p>12V27/8W/12V27/8W/12V27W/12V27W</p>		
<p>222-1915-UE NUBIRA 1800 CC TAIL LAMP R 96551224 L 96551223 6PCS 5.16CFT</p>  <p>P21/5W/P21/5W/P21W/P21W/PY21W</p>		